Copy for Dale Susan ("S. 80)
FIELD INVESTIGATION REPORT (FINAL;
CONCERNING

DISTRIBUTION OF LEAD (Pb)

AT

U.S. SMELTING LEAD REFINING CO.

BY

HAZARDOUS WASTE INVESTIGATIONS SECTION EEI BRANCH OF S&A DIVISION - REGION V

REPORT DATE: August 27, 1980
REPORT AUTHOR: Dr. Robert J. Gnaedinger, Jr.



IN-20-09

### 1 IDENTIFICATION OF ORGANIZATIONS

1.1 U.S. Smelting Lead Refining Company East Chicago, Indiana

### 2 DATES ON SITE

April 8-9, 1980 - Tuesday and Wednesday

### 3 PARTICIPANTS

- 3.1 <u>U.S. Smelting</u>
  Mr. R. Derek Steels, Plant Engineer
- 3.2 East Chicago Air Quality Control Agency
  Mr. Ali Khan
- 3.3 <u>U.S. EPA Region V</u>
  Dr. Robert J. Gnaedinger, Jr., Physical Scientist Mr. Ron Lillich, Biologist
  Ms. Erin Moran, Geologist

### 4 PURPOSE OF SITE INVESTIGATION

The primary purposes of the investigation were to confirm the findings of an earlier non-sampling inspection by Mr. Robert L. Stone and Ms. Elissa Brown of the Air and Hazardous Materials Division, to obtain samples for chemical analysis in order to determine the extent to which lead was moving off from the site, and to make a photographic record of site conditions.

### 5 SUMMARY OF INFORMATION OBTAINED

History of site, observations, photographs, and copies of some records were obtained. In addition, samples of soil, water and waste were obtained from on site as well as from the adjacent Grand Calumet River, both above and below the site, and from the Indiana Harbor Canal at 151st.

### 6 LIST OF FIGURES

- Photographs 2-5, clockwise from upper left; from center of lead smelting slag fill area; Tuesday, April 8, 1980.
  - View of lead slag pile "No. 1" (from East side of pile); Sample 1 from the pile; Ali Khan of E. Chicago Air Quality on left and Ron J. Lillich of U.S. EPA, Region V, on right. Photographed by Robert J. Gnaedinger, Jr. of the U.S. EPA, Region V; 1:16 p.m.



- 3. View to NNE of lead slag, of drums and of plant beyond on left and in center; from East side of pile 1; 1:17 p.m.
- 4. View to NNW of lead slag and of plant beyond; from East side of pile 1; 1:19 p.m.
- 5. View to SW of edge of slag fill in marsh reeds; from West side of slag fill; 1:21 p.m.


## FIGURE 2 Photographs 7, 8 and 9, clockwise from upper left; Tuesday, April 8, 1980:

- 7. View to NW from West side of lead slag fill area; empty drums lie S of the concrete shipping/receiving dock; tree in center of picture is at the approximate location of the exit of a storm drain which extends North beneath dock and beneath buildings beyond. A pool in the reeds in the foreground is the source of water specimens referred to as "effluent" in reports submitted by U.S. Smelting to the State of Indiana. Our Sample 17 came from this pool. 1:27 p.m.
- 8. View to N from West side of lead slag fill area; plant is in background; U.S. EPA personnel are in yellow protective jackets in the left background; Ali Khan of E. Chicago Air Quality is on the right. No smoke from the tall stack was visible during our inspection on April 8-9, 1980. 1:28 p.m.
- 9. View to NNW from shipping/receiving dock. Processed lead ingots are on dock ready for shipment. Sample 2 came from 6" vertical pipe at bottom of manhole; a lower storm drain pipe reportedly is present below the manhole being connected to the base of the manhole via the 6" vertical pipe. This lower drain reportedly leads into the marsh at the South edge of the concrete dock area. 1:39 p.m.

# FIGURE 3 Photographs 10, 11 and 12, clockwise from upper left; Tuesday, April 8, 1980:

- 10. Looking South towards pussy willows in bloom; from South side of EW portion of the U.S. Smelting Canal. 2:00 p.m.
- 11. Looking Northwest from Southeast corner of intersection of the Grand Calumet River (on left) and the U.S. Smelting Canal(on right) River flows towards upper right; direction of flow in the canal is uncertain. 2:08 p.m.
- 12. Looking North across U.S. Smelting Canal at its mouth. Ron Lillich is shown with water sampler just used for collecting Sample 3 at the mouth. Muskrat surfaced at edge of Canal, then quickly reversed his direction, underwater.

- FIGURE 4 Photographs 13, 14, 15 and 16, clockwise from upper left; Tuesday, April 8, 1980:
  - 13. Looking South from land path along the South side of U.S. Smelting Canal. Slag, firebrick and barrels are remains from long past dumping practices. (Plant reportedly has been operating on this site since 1906.)



- 14. Looking NE across marsh, reeds and water towards plant from land path along South side of Canal; shot from location shown in Photograph 13. 2:20 p.m.
- 15. Oil slick on Canal surface near plant; surface flow of Canal appears to be towards the plant (upper right) from the Grand Canal at this point and time. 2:25 p.m.
- 16. Location from which Sample 5 was taken; this was a very wet soil sample from the marsh on the NW side of the Canal. Marsh water is evident (gray-blue patches). Location is near the point at which the Canal changes direction. Sample 4 was obtained from a similar location on the SE side of the Canal.
- FIGURE 5 Photographs 19, 18 and 24, clockwise from upper left; Tuesday, April 8, 1980 and Wednesday, April 9, 1980:
  - 19. Looking NW from the North side of the engineering office building, after rainstorm. Piles of cinders, slag and scrap steel. 3:17 p.m., April 8, 1980.
  - 18. Small pool in marsh land just South of machine shop and waste piles South of shop. Sample #8 was taken from this pool. Bright red-orange iron oxide stain covers center of bottom of pool. 3:40 p.m., April 8, 1980.
  - 24. View towards ESE from the head waters of the U.S. Smelting Canal; from West side of Canal. 4:45 p.m., April 9, 1980.
- FIGURE 6 Photographs 17, 20, 6 and 1, clockwise from upper left; Tuesday, April 8, 1980:
  - 17. Looking E from location Southwest of Machine Shop. Ground surface is slag; pile of air filtration bags from exhaust from smelting furnaces at left center. 3:17 p.m.
  - 20. Looking W from NS road just W of Main Office. Rinsed battery casings, from used batteries, being discharged to dump area for future pickup. 3:55 p.m.
  - 6. Looking SE from slag-filling site towards boundary of slag and reed-covered marshland. Railroad and Kennedy Avenue in background. Kennedy Avenue bridge across Grand Calumet River is under re-construction.

- 1. Looking S along storm water discharge ditch, which runs parallel to and West of railroad. Photo taken near North end of ditch. Sample #18 taken at this location on April 9, 1980.
- FIGURE 7 Photographs 21, 22 and 23, clockwise from upper left; Wednesday, April 9, 1980:
  - 21. Looking NNW from railroad bridge at Grand Calumet River Crossing, adjacent to Kennedy Avenue. U.S. Smelting plant in background with lead slag fill margin with water evident. ~ 1:05 p.m.
  - 22. View of railroad bridge looking SW from Kennedy Avenue, where new automobile bridge is presently under construction. Samples #9. and #10 were taken from the center of the railroad span. ~ 1:10 p.m.
  - 23. View of 151st Street bridge where it crosses the Indiana Harbor Canal. View is towards SE from NW quadrant. U.S. Van on the bridge. 2:50 p.m.
- Results of Analyses of Water Samples for the General Chemical Parameters: Specific Conductance, Sulfate, Chloride, pH and Fluoride.
- FIGURE 9 Results of Analyses of Samples for total Lead, Arsenic and Antimony.
- FIGURE 10 Map of Site, from U.S.G.S. 7-1/2 Minute Topographic, Gary and Vicinity, Indiana.

#### 7 LIST OF SAMPLES

Samples S01 through S08 were taken on April 8, 1980; Samples S09 through S19 were taken on April 9, 1980.

SAMPLE NUMBER	TIME OF COLLECTION	IDENTIFICATION
sed 80VG04S01 sed 80VG04S02 water 80VG04S03	1:15 p.m. 1:50 p.m. 2:30 p.m.	Water from U.S. Smelting Canal at Junction with with the Grand Calumet River
Aed 80VG04S04 Aed 80VG04S05	2:45 p.m. 2:45 p.m.	Salls Sample from Marsh on SE Side of Canal Sample from Marsh on NW Side of Canal
peditul 80VG04S06	3:00 p.m.	the buildings of the site.
∆r £ 80VG04S07	3:30 p.m.	from Big House
wale 80 V G 0 4 S 0 8	3:40 p m.	Water Sample from small pond SW of Engineering Office Building
;ાતમાં <b>80VG04S09</b>	12:15 p.m.	Water Sample from Grand Calumet River at Kennedy Avenue Bridge at ~ 1 ft. depth
sed 80VG04\$10	1:00 p.m.	Kennedy Avenue Bridge

SAMPLE NUMBER	TIME OF COLLECTION	IDENTIFICATION
12.2 80VG04S11	2:30 p.m.	Water Sample from Indiana Harbor Canal at 151st Bridge at ~ 1 ft. depth
رن ه <sup>اری ا</sup> 80۷G04S12	2:45 p.m.	Bottom Water Sample from Indiana Harbor Canal at 151st bridge
ر بر ما <sup>لحاد</sup> 804G04S13	3:15 p.m.	Water Sample from Grand Calumet River at Indianapolis Boulevard at ~ 1 ft. depth
pod 80VG04S14	3:35 p.m.	River at Indianapolis Boulevard
water 80vG04S15"	4:30 p.m.	"Influent"; Water Sample from W side of Canal at N End
Add 80VG04S16	4:30 p.m.	from W side of Canal at N End
<b>აი₩80VG04S17</b>	4:40 p.m.	"Effluent"; Water Sample from Marsh, E of Drum Pile and S of Receiving Dock
water 80VG04S18.	4:45 p.m.	Water Sample from Drainage Ditch on East, N End
,,;.4 ₹€€80VG04S19·	3:05 p.m.	Water Sample from Cold Water Tap in Engineering
102 10 80 VG04518.	(Blank)	Building

### 8 RESULTS OF THE CHEMICAL ANALYSES OF SAMPLES

8.1 Analyses of Water Samples for the General Chemical Parameters:
Specific Conductance, Sulfate, Chloride, pH and Fluoride.

Seven (7) water samples were tested for the above parameters. The results of the testing are tabulated in Figure 8.

If we consider, for the moment, that the surface water from the Granc Calumet River at Kennedy Avenue (where it flows West adjacent to the site) is our norm, then we can see that all of the other samples have higher concentrations of sulfate, chloride and fluoride, and, consistently, higher values for specific electrical conductance.

The most contaminated <u>off-site</u> water is that obtained from the Grand Calumet River at Indianapolis Boulevard. This water was flowing Eastward towards its juncture with the East branch of the Grand Calumet at the West end of this site. There the two flows combine to deliver their water to the Indiana Harbor Canal and thence to Lake Michigan.

However, the U.S. Smelting site appears to be making significant contributions of chloride, sulfate and fluoride ions to the Grand Calumet River and to be adding acids, as well, as evidenced by the low pH values and the high chloride, sulfate and fluoride values found in the "Effluent (S17) and in the East Drainage Ditch (S18).

The high sulfates are most probably arising from the used lead storage batteries which are reprocessed on site; these contain sulfuric acid solutions which are reportedly neutralized on site using limestone. The resulting calcium sulfate is rather insoluble and is normally removed, off-site, by Industrial Disposal Company. It is clear, however, that the reutralization process was ineffectively operating at the time of our inspection.

We believe that the high fluorides occur because of their presence in materials brought on site for recovery. Chloride ion, as well, appears to be contributed by on site processes. The chloride concentration found in the Grand Calumet at Indianapolis Boulevard is, of course, much larger than any of the on site concentrations.

### 8.2 Analyses of Samples for Total Lead, Arsenic and Antimony

These results are given in Figures 9-1 and 9-2. As expected, the lead concentrations varied over a tremendous range, i.e. from 29.00% in the flue dust to less than 2 ppb in water from the cold water tap. The lowest value in the environmental samples was 27 ppb in the "Influent" water from the North end of the U.S. Smelting Canal. It might be noted that none of the values for lead concentration in the "Influent", as analyzed by U.S. Smelting Lead Refining Company, the parent company, were as low as this value; the lowest in the report copies from U.S. Smelting Lead Refining Company in our possession was 60 ppb lead.

Though we have questioned the value for the lead concentration in the "Influent." the concentration of 3400 ppb in the "Effluent" suggests that lead <u>is</u> flowing outward from the plant area by this route. It may in fact be so that it does not reach the Grand Calumet River, but is retained on the marshland, which is owned by U.S. Smelting.

Similarly, the lead concentration at the North end of the East drainage ditch was rather high at 1800 ppb, though <u>no flow</u> in this ditch was obvious. Rather more striking in this case was the very large arsenic concentration of 5800 ppb; this could be attributed to the very low pH found in the water at this location; highly acid conditions increase the solubilities of most metallic oxides.

We have no data indicating the rate at which lead <u>from the slag pile</u> is moving into the marsh nor indicating the rate of lead movement from the marsh into the Grand Calumet River.

In this connection we should re-note that Robert L. Stone's map indicates that the present slag heap does not extend into the flood plain, though it still appears that slag is being dumped into the marshland. We have checked neither elevations nor flood plains with Corps of Engineers maps in this regard, though the presence of marsh water adjacent to the slag would suggest that the flood plain does include portions of the marsh now covered with slag.

The analysis of Sample SO6 is rather significant; a lead concentration of 16% is indicated. The sample is a composite of surface samples taken at various locations around the operating portions of the site; Store had requested that we obtain such a composite. We suspicion that it is related to the gray pall that covered the roadways and the immediately adjacent ground. It appeared to us as if lead flue dust had been casually hauled around in a front end loader, for example, with excessive loss by spill or by wind. This is a point of major concern to us since it represents one of the more hazardous aspects of this size.

Substantial information is present on these data sheets; the expected ubiquitous distribution of lead was found. We compared the results we obtained for River and Canal samples with data from monthly samplings during 1978 by the Division of Water Pollution Control, Indiana State Board of Health. There was reasonable agreement between their results and ours. Only one location was precisely common to their investigations and ours -- the Grand Calumet River at Kennedy Avenue. Good agreement was found between the two sets for specific conductance, sulfate, chloride and pH; however, the lead concentration found in our sample was ~2 times the maximum value found in 1978 by Indiana.

### 9 CONCLUDING COMMENTS

- 9.1 The Company is in contact with and is operating with the knowledge of the State of Indiana, Stream Pollution Control Board.
- 9.2 The Company admittedly does have problems with their flue dust collection system, resulting in occasional failures.
- 9.3 The dust along the internal roadways has a very large lead concentration. Its presence and the <u>processes</u> and handling methods leading to its presence represent serious hazards, especially to plant personnel. 'lant personnel all wear dust masks around their necks, but it is not clear how frequently they are in proper use around their noses and mouths.
- 9.4 The Company appears to have problems in achieving full and effective neutralization of the sulfuric acid waste.
- 9.5 We are concerned that excessive amounts of fluoride may be moving off the site into the Grand Calumet River.
- 9.6 We are concerned that excessive amounts of lead and arsenic may be moving off the site into the Grand Calumet River.
- 9.7 We are concerned about the health of present employees; perhaps all should be tested for the lead content in their blood.
- 9.8 We are seriously concerned about the location of this site and about its contribution of lead to the environment, even though it has been in operation since 1906.
- 9.9 We are semiously concerned about the high lead levels in the Grand Calumet River bottoms. Accidental spills into the River of materials with a high affinity for lead could solubilize large amounts of lead from the bottoms into the river water.
- 9.10 We are seriously concerned about the high concentration of lead found in the West branch of the Grand Calumet River and in the Indiana Harbor Canal at 151st Street. In spite of the relatively low values (20 ppb) for lead reported for the Indiana Harbor Canal near its outflow into Lake Michigan, we suspect that a stead/outpouring of lead into Lake Michigan is occurring.

D. U. NUMBER			- Carrier - Carr		T. G	Account No		-	Smellone RAPA
i zrameter lia.	<u> </u>		<u> </u>	00095	00945	00940	00956	96416	J-L
CDO Sample Log Number				Specific Conductance	Sulfate	Chloride	Total Silica as Sin <sub>2</sub>	Alkalinity as CaCO <sub>3</sub>	PH I,
Units				· punhos/cm , at 25°	mg/1	niq/1	mg/l		
551161555	80VG04	309 Km	d Calimett	480	50.	/ 36			7.0 1
ESVACAZIL	80VG 04	S11 151	THE HIKAUR CAN	1500.	58	61		ļ	711
70 V404 SIA	80VG 04	312 IN	BOTTOM WATER		58	60		1	- 71
2011-04513	80VG 04	5/3 870	na Calumet	1900	173	390		1 +1	711
31604515	2016 04	5/5 "3	VILLING CANAL	980 1	189 1	77		H	6.7
101304517	80 KG 04		Quent March	2600 1	1410	71		1 1 1	15.9 12
201604512	BOVG 04	5/8 DI	East Side	7800	5,000	210			123
				4-14-80	4/17/80	1/17/80			4-14-19 1 4
			11	V 1					
								4 2	Y
			7 3					123	S. T.
	Conte	-7 1 NOV	fee March	و و و من من من من	ر دوده ای تاسر ا	029 14	ingent	\$ 60° E	328
					1			11 4	<b>1</b>
.,								7,2	
1								Y	
						·			
			1					÷	
						; .			

DIVISION B	RANCH E	cre-lecke	Sampling Date 8			,		_	Analusia	
D. U. NUMBER		T EEIB ZA		Namen You	CHAPE	irrival da     Account    		4180 North Year	Study	Sameling
Far	01105	01002		01034	01037	01042	01045.	01051	, 01055	
CDO Sample Log Number	Total :Aluninum	Total Arsenic		Total Antimeny	Total Cobalt	Total Copper	Total Iron	Total Lead	Total Manganese	
201604 inits	µg/1	μg/l	Service Servic	; pg/1	µg/1	, µg/1	µg/1	μg/1 Βωσο	μ9/1	
249501	1/3/11	751	SLAG FILE	3937	41 2 5 ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° °			Jan Jan	History.	SEDIMENT
11507502		sample.	STORM DRAIN:	sample				sample		SUPPLET
Vix.4 So3	187.30	3.6 10	Vis, Smitt Cone	K2 ppla	- 4		A	152 mb		100000
1: 6:34504		45	Marsh Soil Sonal	126 2	1 41 4 45 41			2300	1	550111511
11674505	is a constraint	24007	Motor Sail	87.27	77.			700	1/4 	SEDIMENT
:: 16 CHSOL	7 g . 1 . 1 . 1 . 1	1600 7/4	SURPACE SCIL	12207		1 A 2 4 1	Probein 3	109000	age (1) k A processor (1) k A processor (1) k	SEDIM
०१५०५८०७		6300 T	FLUE DUST	1810	programme and	. 4049.1		2900cu	************	SEDIMENT -
11504508		- 47 ppb	SMALL POND	850 ppb	Will service			2350ppb	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	WATER !
11264509		طام م 42 ا	Grand calumet	2.7ppb			71 yy	1987		WATER- T
- 534510	•	55 7%	" Bittom	K.4 7			10 m	1790 mg	Sect Josephia	SEDIHUM
27604710		. 46 mg	Duplicate,	247		3		900		SEOINERA -
11604511	*	- 5,9 ppb	Indiana Herbers	.K2 ppb	I.a.			مامرم 187	3 2	WITTER
0.001512		طام 0,4	" Battom Wat	K2 mb		1980	Street 50603	15700		LIMITE
37634513		- 11 ppb	mond defunct	30,06	I.n.		9	1/290 76		I WATER
0:1604514		141 mg/	" Bettern	3.5		1AY	49.6	1860		1 5001110000
5740 +D14	7	41 2	Duplicates	3.2	<u> </u>	2	350	800 00	;	SEPHANAT
V434515		- 270 mb	"Influent"	70.5 pub				27 10		V1117872
31664516	,	1700	Canal Bottom	393 7			14	8500		SHTOIMSI.
21/10/16		1700	Dunkicutos	437				13000		KEDIMAT !
		120 5/480		5/6/80			200	5/4/80		
note;	Ca, S	6 and 1	b may all s	ie presen	nd in h	ugh c	ronce	utravar	Government	rinting Offices 1971-550-687/21

	311	111	1	· 4 fa ,	01034	01037	Account No	01045	01051	01055	· · · · · · · · · · · · · · · · · · ·
DO 53- 10 Log Kaiter	istal Aluminus	Tirat Arsenic.			Profint Admin	Yotal Cobalt	Total Copper	Total Iron	Total Lead	Tutal Manganese	
units	μ <b>g.′</b> Ί	· µg/1			<b>р</b> 9/1	pg/1	pg/1	µg/1	μg/1	µ9/1	
457		- 280 ppb	"Efflue	A" . i.	196 yeb				3400 pt		121.362.77
UC19		15800 ppb	C. Drain			, .			اطرم 1800		WATER
04519	. : : :	3,6 0,06	Coldwat	Tap	K2 ppb				K2 pplo		WETTER
Raol		de 0.E	Blank		K2 pplo				K2 pale		1 chim
		20 5/6/80							5/4/50	<u>i</u>	
				-							
									<u> </u>		
						:					
										"	
	! 	-						<u>  </u>			\
		-11/2/2	1.2.	The series	12771	10 1 mg/	ا مرووم	417-3	pen	129 1	entry
	<u> </u>								-		
					-	· .			-		28 3
		+							<del>  </del> -		\$ 3°
						-					S = 30
			-		-			<del> </del>			O 5 5 5 5
1 1				·	-				-		353

# FILLD INVESTIGATION PEPORT Fobert Chacolinger August 2.7, 1980

IGE	NERAL	ن ن			
		. 1	Arsenic ingly		Lead (mg/kg)
sed	501	slag heap	751	3.93	50,000
sed	S07	flue dust	6300	1,810	290,000 -
sed	X2	storm drain	1,66	1220	160,000
Aed	S06 518	comp surf. soil water from drainay	1,600 tamuall	1220 815 mll	1,800 mg/l
water	210	ditchon E, N end	5800 ug/l	7	1,000,312
water	519	faucet in Eng Bldg.	3.6 usil	K2 ugll	KZ usle
water	508	Fond SW of Eng Blag	47 mil	K2 right 850 mg/e	350 mll
		0 0		U	0
M	arsh				
sed	* 504	Soil from marsh	45	1260	7,300
		on St side of canal			
sed	505	Soil from marsh	2400	87.2	990
•	517 o <sup>ji filio</sup> ra	on NW side of canal	100 110	196 1110	3460 18
water	217	Nater sample from	180 y/l	196 Ml	3,400m/l
		marsh, S & rec. dock			
_					
(	ANAL				
	<.15- " th	in N orde & canal at	220 10	70 5 milo	72 10
water	S16	White of canal at White of canal at Canal at junction	270 mg/2 1,700/1,700	70.5 W/2 393/437	27 wll 8,506/13,000
ARC	503	Canal at junction	3.6 mjl	K2 ugle	52 ull
water		w Grand (al. River		J	Ü
water	ZIVER			- 7 / 6	
water	509	From Gr. Cal. River	4.2 m/x	2. tug/2	98mg/2
sed	S10 '	Lat Kennely Ave Bicke	55/46	K.492.4	710/900 187 mg/l
water water	512 den	Lat Kennedy Ave Bicke St. From Ind. Harbor land at 151 <sup>st</sup> St. Bridge	5.9 mg/l	K2 w/k	157 ucll
water	513	Stiern Gr. (al. River ut	4.0 mll	K2 m/l	290 roll
sed	514	I Indianapolis Boulevard	41/41	3.0 M/l 3.5/3.2	860/800
/3~6	-	. O		I	• •